



CENTURY MINE STREAM MITIGATION PHOTOGRAPHS
Piney Creek



Photograph: 54
PCSL-9: Partially successful bank grading, coir log



Photograph: 55
PCSR-4: Successful log vane and J-hook



Photograph: 56
PCSR-4: Unsuccessful stream bank stabilization



Photograph: 57
PCSR-7: Boulder toe protection



Photograph: 58
PCRS-8: Unsuccessful stream bank stabilization



Photograph: 59
PCSR-11: Unsuccessful log vane and J-hook